

Interstate Designation Issues



VERTICAL CLEARANCE DEFICIENCIES

Disclaimer Statement:
This is not a proposal

This is a display of vertical clearance deficiencies for bridge structures if strict Interstate standards were applied.
Future negotiations with the U.S. Department of Transportation may eliminate some or all of the listed locations.

Tag #	PM	Location Description
27	22.76	Applegate Rd OC
28	20.52	Buhach Rd OC
29	15.78	Route 99/140 Sep
30	15.15	O Street UC
31	13.86	Rt 99/140 Separation

